

C32 Protection Board Connector Pin Assignments

C32 Connector

No Connect	1	28	No Connect
Port E0	2	27	Port AD0
Port E1	3	26	Port AD1
Port T7	4	25	Port AD2
Port T6	5	24	Port AD3
Port T5	6	23	Port AD4
Port T4	7	22	Port AD5
Port T3	8	21	Port AD6
Port T2	9	20	Port AD7
Port T1	10	19	Port M5
Port T0	11	18	Port M4
Port M0	12	17	Port M3
Port M1	13	16	Port M2
Ground	14	15	Ground

Ribbon Cable Goes----->